DECEMBER 1994

REPORT NO. 95-06

CONTAINER LOAD TRAILER (CLT) DEMONSTRATION



19950828 064

Prepared for:

U.S. Army Armament, Munitions and Chemical Command ATTN: AMSMC-TM Rock Island, IL 61299-6000




DTIC QUALITY INSPECTED 5



CENTER AND SCHOOL

VALIDATION ENGINEERING DIVISION SAVANNA, ILLINOIS 61074-9639

DISCLAIMER NOTICE



THIS DOCUMENT IS BEST QUALITY AVAILABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF COLOR PAGES WHICH DO NOT REPRODUCE LEGIBLY ON BLACK AND WHITE MICROFICHE.

AVAILABILITY NOTICE

A copy of this report will be furnished each attendee on automatic distribution. Additional copies or authority for reprinting may be obtained by written request from Director, U.S. Army Defense Ammunition Center and School, ATTN: SMCAC-DEV, Savanna, IL 61074-9639.

DISTRIBUTION INSTRUCTIONS

Destroy this report when no longer needed. Do not return.

Citation of trade names in this report does not constitute an official endorsement.

The information contained herein will not be used for advertising purposes.

UNCLASSIFIED SECURITY CLASSIFICATION OF THIS PAGE

REPORT DOCUMENTATION PAGE						Form Approved OMB No. 0704-0188		
1a. REPORT SECURITY CLASSIFICATION				1b. RESTRICTIVE MARKINGS				
UNCLASSIFIED								
2a. SECURITY CLASSIFICATION AUTHORITY				3. DISTRIBUTION / AVAILABILITY OF REPORT				
2b. DECLASSIFICATION / DOWNGRADING SCHEDULE				UNLIMITED				
4. PERFORMING ORGANIZATION REPORT NUMBER(S)				5. MONITORING	ORGANIZATION RE	PORT NUI	MBER(S)	
95-06								
6a. NAME OF PERFORMING ORGANIZATION U.S. Army Defense Ammunition			6b. OFFICE SYMBOL (if applicable)	7a. NAME OF MONITORING ORGANIZATION				
Center and School			SMCAC-DEV					
	MCAC-DEV			7b. ADDRESS (Ci	ity, State, and ZIP Co	de)		
Savanna, 8a. NAME OF FUN	IL 61074-963		8b. OFFICE SYMBOL	9. PROCUREMENT INSTRUMENT IDENTIFICATION NUMBER				
ORGANIZATIO	N	o. Troodicale	VI 110011101112111 101					
il -	y Armament, l		AMSMC-TM					
8c. ADDRESS (City	ical Comman			10. SOURCE OF	FUNDING NUMBERS	 S		
	MSMC-TM	,		PROGRAM	PROJECT NO.	TASK NO).	WORK UNIT
	nd, IL 61299-	6000		ELEMENT NO.				ACCESSION NO.
11. TITLE (Include				<u> </u>				
· ·	Load Trailer		nstration					
12. PERSONAL AU	THOR(S)							
Quinn D.	Hartman							
13a. TYPE OF REF	PORT	13b. TIME COVE	RED	14. DATE OF REPORT (Year, Month, Day) 15. PAGE COUNT				
Final FROM —		FROM -	то	1994 December			<u> </u>	
16. SUPPLEMENTA	ARY NOTATION							
	COSATI CODES		18. SUBJECT TERMS	(Continue on revers	e if necessary and ide	entify by bl	ock numb	er)
FIELD	GROUP	SUB-GROUP	_					
1			tify by block number)					
			nition Center and					
			anufactured by ES					
system capable of lifting International Organization for Standardization (ISO)-compatible containers by the								
			ading and unload					
consists of	of two units ea	ch with self-c	ontained hydraul	ic systems pov	vered by small	diesel	engine	s. Load
capacity f	for the CLT is	50,000 pound	ds while the weig	ht of the CLT	is only approx	imately	12,60	0 pounds.
Results from the demonstration indicated a few tolerance problems that would need to be studied before								
possible use of the system in ammunition logistics is considered.								
OO DIOTRIBUTION	L/ AVAIL ADD TD/ CT	ADOTDACT		21 ARSTRACT S	ECHRITY OF ASSIST	CATION		
20. DISTRIBUTION / AVAILABILITY OF ABSTRACT WUNCLASSIFIED/UNLIMITED SAME AS RPT. DTIC USERS				21. ABSTRACT SECURITY CLASSIFICATION UNCLASSIFIED				
UNCLASSIFIED/UNLIMITED SAME AS RPT. DTIC USERS 22a. NAME OF RESPONSIBLE INDIVIDUAL				22b. TELEPHONE (Include Area Code) 22c. OFFICE SYMBOL				
JEROME H. KROHN				815-273	3-8929		SM	CAC-DEV

U.S. ARMY DEFENSE AMMUNITION CENTER AND SCHOOL VALIDATION ENGINEERING DIVISION SAVANNA, IL 61074-9639

REPORT NO. 95-06

CONTAINER LOAD TRAILER (CLT) DEMONSTRATION

TABLE OF CONTENTS

PART	PAGE NO.
1. INTRODUCTION	1-1
A. BACKGROUND	1-1
B. AUTHORITY	1-1
C. OBJECTIVE	1-2
D. CONCLUSIONS	1-2
2. ATTENDEES	2-1
3. EVALUATION PROCEDURES	3-1
4. RESULTS	4-1
5. PHOTOGRAPHS	5-1

Acces	sion For	1 377					
NTIS	GRA&I	□ 1					
DTIC	TAB						
Unannoumced 🔲							
Justification							
Ву							
	ibution &						
Avai	lability	Codes					
	Avail an	d/or					
318t	Specia	J.					
AI							

PART 1

INTRODUCTION

- A. BACKGROUND. The U.S. Army Defense Ammunition Center and School (USADACS) conducted a demonstration of the Container Load Trailer (CLT) manufactured by ESCO Datron, Aston, PA, 30 November and 1 December 1994. During the two-day demonstration, the CLT was put through a few container handling scenarios in order to assess the capabilities of the system for U.S. Army ammunition logistics system use. The CLT system, as demonstrated, consists of two separate units that can be attached to either end of an ISO-compatible container for towing or can be attached to either side of an ISO-compatible container in order to load or unload the container from a trailer. The CLT units both have stand-alone hydraulic units powered by small diesel engines with a load capacity of 50,000 pounds while only weighing approximately 12,600 pounds. The back section of the CLT system has a hydraulic maneuvering system which allows the back section to be effortlessly positioned by one person. The front section has no maneuvering system with the intention that the towing vehicle would back the front section into position for attachment to the MILVAN. In the event there is no vehicle to position the front section, the unit can be easily maneuvered with three people. The CLT system also has airbrakes on both units with an extension airhose to interconnect the units with the towing vehicle.
- B. <u>AUTHORITY</u>. The test was accomplished IAW mission responsibilities delegated by U.S. Army Armament, Munitions and Chemical Command (AMCCOM). Reference is made to the following:
- 1. Change 4, 4 October 1974, to AR740-1, 23 April 1973, Storage and Supply Activity Operation.

- 2. AMCCOM-R 10-17, Mission and Major Functions of USADACS, 13 January 1986.
- C. <u>OBJECTIVE</u>. To determine possible uses for the CLT handling ammunition-loaded ISO-compatible containers.
- D. <u>CONCLUSIONS</u>. During the demonstration, the following factors affecting the suitability of the CLT for U.S. Army use were noted:
- 1. Tolerance problems with the T-bolts and the M872 semitrailer tiedown fittings will have to be investigated as well as potential problems with other trailers.
- 2. The vertical lift capability of the CLT should be studied if the system is to be used on trailers with a deck higher than the M872 semitrailer.
- 3. Modification of the CLT which would provide for more lateral clearance between the sides of the MILVAN and the CLT during side lifts without sacrificing the vertical lift capability should aid significantly in positioning trailers under the MILVAN.
- 4. Operation of the CLT on soft ground may prove difficult due to the small size dolly wheel on each section of the CLT system.

PART 2

30 NOVEMBER - 1 DECEMBER 1994

ATTENDEES

Quinn D. Hartman

General Engineer

DSN 585-8992

815-273-8992

Jerome H. Krohn

Supervisory General Engineer

DSN 585-8929

815-273-8929

William R. Frerichs

Supervisory General Engineer

DSN 585-8071

815-273-8071

Gregory L. Willis

Industrial Engineer

DSN 585-8075

815-273-8075

SGM Frank W. Brantley

Logistics Management Specialist

DSN 585-8050

815-273-8050

Kevin Mulligan

610-494-8000

Director

U.S. Army Defense Ammunition Center

and School

ATTN: SMCAC-DEV

Savanna, IL 61074-9639

Director

U.S. Army Defense Ammunition Center

and School

ATTN: SMCAC-DEV

Savanna, IL 61074-9639

Director

U.S. Army Defense Ammunition Center

and School

ATTN: SMCAC-DET

Savanna, IL 61074-9639

Director

U.S. Army Defense Ammunition Center

and School

ATTN: SMCAC-DET

Savanna, IL 61074-9639

Director

U.S. Army Defense Ammunition Center

and School

ATTN: SMCAC-AV

Savanna, IL 61074-9639

Engineered Systems

A DATRON Company

2550 Market Street


Aston, PA 19014

Jon France DSN 793-5123 309-782-5123 Commander
U.S. Army Armament, Munitions and Chemical Command
ATTN: AMSMC-TMP-G
Rock Island, IL 61299-6000

PART 3

EVALUATION PROCEDURES

a. <u>ROAD HAZARD COURSE</u>. The CLT, transporting a 20-foot inertly-loaded MILVAN weighing 44,000 pounds, was pulled over a 200-foot-long segment of concrete road which consisted of two series of railroad ties projecting 6-inches above the level of the road surface. The load traversed the course two times, the first time at half-speed and the second time at 6.2 mph (see figure 1).



3-1

b. <u>WASHBOARD COURSE</u>. The CLT, transporting a 20-foot inertly-loaded MILVAN weighing 44,000 pounds, was pulled over the washboard course at a speed which produced the most violent response. The washboard course consists of a 300-foot-long section of rails embedded in concrete with two inches protruding above the concrete and spaced at intervals of 26-1/2-inches (see figure 2).




FIGURE 2

PART 4

RESULTS

During the demonstration, the CLT was put through a variety of container handling sequences that represented "real world" container handling scenarios. All container handling sequences were accomplished with a MILVAN loaded to a gross weight of 44,000 pounds. During the two-day demonstration, the CLT was used to pick up and trailer the MILVAN; pick up and load the MILVAN onto an M872 semitrailer; unload the MILVAN from an M872 semitrailer, and traverse the road hazard course. A demonstration of the CLT towing configuration used when transporting the CLT without a container was also performed.

- a. End Pick Up and Towing of MILVAN. Results revealed no deficiencies of the CLT system. The CLT system easily interfaced with the MILVAN and had no difficulty in raising the MILVAN to transportation height. The timeframe to install the system in this configuration using three people would be approximately 5 to 10 minutes.
- b. Side Lift Loading of MILVAN. Results revealed some clearance and positioning problems associated with backing a trailer into position under the MILVAN. Initially, the CLT system was not able to raise the MILVAN to the required height to back the trailer into position. The MILVAN had to be set back on the ground and all available slack was removed from the chains that attach the CLT units to the bottom ISO corner fittings. After the secondary adjustment, the CLT was able to lift the MILVAN to the necessary height. Trailers with a deck higher than an M872 semitrailer will probably be unable to be loaded with the CLT system. The second problem was due to minimal lateral clearance. The CLT units are positioned 6 8 inches beyond each side of the MILVAN during the side lift so that clearance for the trailer is minimal. Extreme care had to be exercised during the backing of the trailer due to the high center of

gravity (CG) and relatively narrow wheel base of the CLT units with a MILVAN elevated to the height of the trailer deck. The M872 semitrailer collided with the CLT units several times during positioning of the trailer, nearly tipping the MILVAN over. Once backed into position, additional problems arose while positioning the MILVAN onto the corner twist-lock fittings of the trailer. The problem was ultimately resolved by getting the trailer lined up with the front corner twist-lock fittings of the trailer and using the side shifting capabilities of the CLT units to position the MILVAN onto the rear twist-lock fittings. This procedure was only possible due to the fact that the M872 semitrailer has a deck that slopes towards the rear of the trailer. A similar type procedure would probably not work on a trailer with a level deck. The timeframe to install the CLT on the side of the MILVAN and raise it to the necessary height to back the trailer under would be approximately 10 to 15 minutes. Additional time would be required to position the trailer and that would vary significantly depending on the skill of the driver.


- c. <u>Side Lift Unloading of MILVAN</u>. Results revealed some tolerance problems with the T-bolts that attach the CLT units to the lower ISO fittings on the MILVAN. During this phase of the demonstration, the MILVAN was placed onto the M872 semitrailer with a 50,000-pound container handler and removed with the CLT units. While attaching the CLT units to the MILVAN, a tolerance problem between the corner twist-lock fittings of the trailer and the T-bolts from the CLT were noted. The T-bolt could be inserted; however, it could not be rotated. Two of the four T-bolts had to be modified in order to complete the demonstration (see part 5). The tolerance problem was not noted during phase 2 of the demonstration due to the fact that the CLT units were not removed from the MILVAN. Installation time for this procedure would be similar to the previous procedure.
- d. Road Hazard Course. The CLT system and MILVAN were pulled over the road hazard course and the washboard course in order to assess the capability of the CLT for transportation over rough terrain. The first pass over the road hazard course was performed at half-speed. The

second pass over the road hazard course was performed at 6.2 mph. During the last part of the demonstration, the CLT and MILVAN were pulled over the washboard course at 3.3 mph. The CLT operated smoothly over both courses without any deficiencies noted.


e. <u>CLT Configured for Transport Without MILVAN</u>. In this configuration, adaptors were inserted between the two units at the points where the CLT attaches to the bottom fittings on the MILVAN during end lifts. The same T-bolts that were used to fasten the CLT to the MILVAN were used to bolt both CLT units together, allowing the CLT to be connected to the vehicle for towing.

PART 5

PHOTOGRAPHS




AO317-SCN95-60-359 - This photograph shows the CLT system being unfolded from the flat shipping position. Note personnel acting as a counterweight.




U.S. ARMY DEFENSE AMMUNITION CENTER AND SCHOOL - SAVANNA, IL

AO317-SCN95-78-360 - This photograph shows the CLT system during the unfolding from the flat shipping position.




AO317-SCN95-78-419 - This photograph shows the CLT system unfolded to the point where the main wheels have made contact with the ground.




U.S. ARMY DEFENSE AMMUNITION CENTER AND SCHOOL - SAVANNA, IL


AO317-SCN95-78-411 - This photograph shows the CLT system retracting the main hydraulic cylinders, placing the system in an upright position.




AO317-SCN95-60-363 - This photograph shows the front section of the CLT system being manually pushed into position for attachment to one end of the MILVAN. Note the front section of the CLT system has no maneuvering system like the rear section of the system.



AO317-SCN95-78-362 - This photograph shows the front section of the CLT system aligned to the end of the container prior to attachment.




AO317-SCN95-78-412 - This photograph shows the rear section of the CLT system. Note the hydraulic maneuvering wheels next to the main wheels.




U.S. ARMY DEFENSE AMMUNITION CENTER AND SCHOOL - SAVANNA, IL

AO317-SCN95-60-414 - This photograph shows the rear section of the CLT system being maneuvered with the hydraulic maneuvering system.




U.S. ARMY DEFENSE AMMUNITION CENTER AND SCHOOL - SAVANNA, IL


AO317-SCN95-78-415 - This photograph shows the rear section of the CLT system aligned with the end of the MILVAN prior to attachment.



AO317-SCN95-78-407 - This photograph shows the CLT system being attached to the end of the MILVAN. Note how the CLT system is initially hooked into the upper corner fittings.





Note the hydraulic cylinders have been adjusted so the system is now flush against the end of the container, AO317-SCN95-78-406 - This photograph shows the CLT system being attached to the end of the MILVAN. allowing the T-bolts to be inserted




AO317-SCN95-78-409 - After the insertion of T-bolts into the lower corner fittings, the CLT system was ready to raise the MILVAN. U.S. ARMY DEFENSE AMMUNITION CENTER AND SCHOOL -SAVANNA, IL


5-13






AO317-SCN95-60-344 - This photograph shows the CLT system setup for a side lift of the MILVAN. Note the crossbars across the top of the MILVAN. These crossbars keep the CLT units from crushing the top of the MILVAN







lateral tolerance between the semitrailer and the CLT system was minimal, so backing the trailer into position AO317-SCN95-78-346 - This photograph shows the M872 semitrailer being backed under the MILVAN. The was difficult.



AO317-SCN95-60-349 - This photograph shows the wheel chocks that were used to help align the MILVAN corner fittings with the M872 semitrailer tiedown fittings. Note the personnel ladder that is built into the CLT system to provide easy access to the top of the MILVAN in order to connect the crossbars overtop of the MILVAN




AO317-SCN95-78-396 - This photograph shows the amount of metal that had to be removed from the T-bolts due to the tolerance problems with the M872 semitrailer tiedown fittings. This problem was noted when attempting to remove the MILVAN from the trailer.





SAVANNA, IL

raised. In this configuration, it is possible to move the MILVAN laterally as long as movement is restricted to a AO317-SCN95-78-410 - This photograph shows the CLT in a side-lift configuration with the MILVAN paritally straight line.



AO317-SCN95-60-387 - This photographs shows the CLT connected to the MILVAN prior to traversing the road harzard course. Note the air hose connecting the front and rear sections of the CLT system.





AO317-SCN95-60-353 - This photograph shows the CLT system configured for towing without attachment to a MILVAN.